

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION San Marino Unified School District		COUNTY Los Angeles	
SCHOOL SITE Carver Elementary School		SCHOOL TYPE (GRADE LEVELS) K-5	NUMBER OF CLASSROOMS ON SITE 37
INSPECTOR'S NAME Jim Fahey	INSPECTOR'S TITLE Director of Maintenance and Operations	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)	
TIME OF INSPECTION 4/20/2018	WEATHER CONDITION AT TIME OF INSPECTION Warm		

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL NUMBER OF AREAS EVALUATED	CATEGORY TOTALS	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
		GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
↓ 40	Number of "✓"s:	40	40	40	40	40	40	40	4	40	40	40	40	40	9	40
	Number of "D"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/As:	0	0	0	0	0	0	0	36	0	0	0	0	0	31	0
Percent of System in Good Repair Number of "✓"s divided by (Total Areas - "NA"s)*		100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
Total Percent per Category (average of above)*		100.00%			100.00%	100.00%		100.00%	100.00%		100.00%		100.00%		100.00%	
Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%		GOOD			GOOD	GOOD		GOOD	GOOD		GOOD		GOOD		GOOD	

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:

DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	→	100.00%	SCHOOL RATING**	→	EXEMPLARY
--	---	---------	-----------------	---	-----------

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:

PART II: EVALUATION DETAIL

Date of Inspection: _____

School Name: _____

CATEGORY AREA	1 GAS LEAKS	2 MECH/HVAC	3 SEWER	4 INTERIOR SURFACES	5 OVERALL CLEANLINESS	6 PEST/VERMIN INFESTATION	7 ELECTRICAL	8 RESTROOM	9 SINKS/ FOUNTAINS	10 FIRE SAFETY	11 HAZARDOUS MATERIALS	12 STRUCTURAL DAMAGE	13 ROOFS	14 PLAYGROUND/S CHOOL GROUNDS	15 WINDOWS/ DOORS/ GATES/FENCES
Class Room - 1	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 10	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 11	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 12	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 13	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 14	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 15	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 16	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 17	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 18	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 19	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															

Marks: ✓ = Good Repair; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional Area Lines as necessary.

PART II: EVALUATION DETAIL

Date of Inspection: _____

School Name: _____

CATEGORY AREA	1 GAS LEAKS	2 MECH/HVAC	3 SEWER	4 INTERIOR SURFACES	5 OVERALL CLEANLINESS	6 PEST/VERMIN INFESTATION	7 ELECTRICAL	8 RESTROOM	9 SINKS/ FOUNTAINS	10 FIRE SAFETY	11 HAZARDOUS MATERIALS	12 STRUCTURAL DAMAGE	13 ROOFS	14 PLAYGROUND/S CHOOL GROUNDS	15 WINDOWS/ DOORS/ GATES/FENCES
Class Room - 2	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 20	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 21	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 22	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 23	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 24	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 25	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 26	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 29	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 3	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 30	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															

Marks: ✓ = Good Repair; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional Area Lines as necessary.

PART II: EVALUATION DETAIL

Date of Inspection: _____

School Name: _____

CATEGORY AREA	1 GAS LEAKS	2 MECH/HVAC	3 SEWER	4 INTERIOR SURFACES	5 OVERALL CLEANLINESS	6 PEST/VERMIN INFESTATION	7 ELECTRICAL	8 RESTROOM	9 SINKS/ FOUNTAINS	10 FIRE SAFETY	11 HAZARDOUS MATERIALS	12 STRUCTURAL DAMAGE	13 ROOFS	14 PLAYGROUND/S CHOOL GROUNDS	15 WINDOWS/ DOORS/ GATES/FENCES
Class Room - 31	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 32	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 33	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 34	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 35	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 36	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 37A	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 37B	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Class Room - 38	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 4	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 5	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															

Marks: ✓ = Good Repair; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional Area Lines as necessary.

PART II: EVALUATION DETAIL

Date of Inspection: _____

School Name: _____

CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/S CHOO/ GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Class Room - 6	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 7	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 8	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Class Room - 9	✓	✓	✓	✓	✓	✓	✓	NA	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Restrooms by kind.	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
COMMENTS:															
Restrooms north west of library	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
Staff Restroom by libary	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	NA	✓
COMMENTS:															
COMMENTS:															
COMMENTS:															
COMMENTS:															

Marks: ✓ = Good Repair; D = Deficiency; X = Extreme Deficiency; NA = Not Applicable
 Use additional Area Lines as necessary.