FACILITY INSPECTION TOOL SCHOOL FACILITY CONDITIONS EVALUATION (REV 05/09)

Page 5 of 6

(REV 05/09)															Page 5 of 6
PART II: EVALUATION D	ETAIL	Date	of Inspection:	11/04/09		School Name:	Valentine	Element	arv Schoo					_	
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg A	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Diag A	COMMENTS:														
Bldg B	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg C1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg C2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	√	✓
	COMMENTS:														
Bldg C3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg C4	✓	✓	✓	✓	√	√	✓	✓	√	√	✓	✓	√	✓	✓
	COMMENTS:														
Bldg D1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	√	✓
	COMMENTS:														
Bldg D2	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg E	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg F	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg G	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:		r		1					ı	r	ı	1		1
Bldg H	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														
Bldg J	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
	COMMENTS:														

FACILITY INSPECTION TOOL SCHOOL FACILITY CONDITIONS EVALUATION (REV 05/09)

age 5 of 6

(REV 05/09)															Page 5 of 6
PART II: EVALUATION D	ETAIL	Date	of Inspection:	11/04/09	-	School Name:	Valentine	Element	arv Schoo	ol					
CATEGORY	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15
AREA	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOM	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/ DOORS/ GATES/FENCES
Bldg J1	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
Brag 07	COMMENTS:														
Bldg J2/3	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2/ag 62/6	COMMENTS:		_												
Bldg K	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2.ag /t	COMMENTS:		_												
Bldg L	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓	✓
2.ag L	COMMENTS:														

Marks: $\sqrt{\ }$ = Good Repair; **D** = Deficiency; **X** = Extreme Deficiency; **NA** = Not Applicable Use additional Area Lines as necessary.

FACILITY INSPECTION TOOL(FIT) SCHOOL FACILITY CONDITIONS EVALUATION

(REV 05/09)

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	
San Marino Unified		Los Angeles	
SCHOOL SITE		SCHOOL TYPE (GRADE LEVELS)	NUMBER OF CLASSROOMS ON SITE
Valentine Elementary School		K-5	34
INSPECTOR'S NAME	INSPECTOR'S TITLE	NAME OF DISTRICT REPRESENTATIVE ACC	COMPANYING THE INSPECTOR(S) (IF APPLICABLE)
Gerald Schober	Construction Manager		
TIME OF INSPECTION	WEATHER CONDITION AT TIME OF INSPECTION		
7 am to 12 pm	Fair		

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL	CATEGORY	A. SYSTEMS			B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL	
NUMBER OF AREAS EVALUATED	TOTALS	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
	Number of "√"s:	7	7	7	7	7	7	7	7	7	7	7	7	7	7	7
₩	Number of "D"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
7	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
	Number of N/As:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Number of "	em in Good Repair ✓"s divided by as - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	t per Category of above)*		100.00%		100.00%	100.	00%	100.00%	100	.00%	100.	00%	100.0	00%	10	0.00%
GOOD = FAIR = 7	Rank (Circle one) GOOD = 90%-100% FAIR = 75%-89.99% POOR = 0%-74.99%			GOOD	GOOD		GOOD	GOOD		GOOD		GOOD		GOOD		

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	→	100.00%	SCHOOL RATING**	→	EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75.%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:	