STATE ALLOCATION BOARD OFFICE OF PUBLIC SCHOOL CONSTRUCTION

FACILITY INSPECTION TOOL(FIT) SCHOOL FACILITY CONDITIONS EVALUATION

(REV 05/09)

05/09)

SCHOOL DISTRICT/COUNTY OFFICE OF EDUCATION		COUNTY	COUNTY			
San Marino Unified School District		Los Angeles	Los Angeles			
SCHOOL SITE	SCHOOL TYPE (GRADE LEVELS) NUMBER OF					
Valentine Elementary		K-5	34			
•	INSPECTOR'S TITLE	NAME OF DISTRICT REPRESENTATIVE AG	NAME OF DISTRICT REPRESENTATIVE ACCOMPANYING THE INSPECTOR(S) (IF APPLICABLE)			
Jim Fahey	Director Maintenance and Operations	Gil Cardenas (Mainten	Gil Cardenas (Maintenance Manager)			
TIME OF INSPECTION	WEATHER CONDITION AT TIME OF INSPECTION					
11/19/2018	Clear					

PART III: CATEGORY TOTALS AND RANKING (round all calculations to two decimal places)

TOTAL CATEGORY		A. SYSTEMS		B. INTERIOR	C. CLEANLINESS		D. ELECTRICAL	E. RESTROOMS/FOUNTAINS		F. SAFETY		G. STRUCTURAL		H. EXTERNAL		
NUMBER OF AREAS EVALUATED	TOTALS	GAS LEAKS	MECH/HVAC	SEWER	INTERIOR SURFACES	OVERALL CLEANLINESS	PEST/VERMIN INFESTATION	ELECTRICAL	RESTROOMS	SINKS/ FOUNTAINS	FIRE SAFETY	HAZARDOUS MATERIALS	STRUCTURAL DAMAGE	ROOFS	PLAYGROUND/ SCHOOL GROUNDS	WINDOWS/DOORS/ GATES/FENCES
	Number of "√"s:	42	42	41	42	42	42	42	8	41	42	42	42	42	42	42
+	Number of "D"s:	0	0	0	0	0	0	0	1	0	0	0	0	0	0	0
42	Number of "X"s:	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
42	Number of N/As:	0	0	1	0	0	0	0	33	1	0	0	0	0	0	0
Number of "	em in Good Repair "√"s divided by eas - "NA"s)*	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	88.89%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%	100.00%
	nt per Category e of above)*		100.00%		100.00%	100.	00%	100.00%	94.	45%	100.	00%	100.0	00%	100	0.00%
GOOD = FAIR = 7	Circle one) : 90%-100% !5%-89.99% 0%-74.99%		GOOD		GOOD	GO	OD	GOOD	GC	DOD	GO	OD	GO	OD	G	OOD

*Note: An extreme deficiency in any area automatically results in a "poor" ranking for that category and a zero for "Total Percent per Category".

OVERALL RATING:	DETERMINE AVERAGE PERCENTAGE OF 8 CATEGORIES ABOVE	→	99.31%	SCHOOL RATING**	→	EXEMPLARY

**For School Rating, apply the Percentage Range below to the average percentage determined above, taking into account the rating Description below.

PERCENTAGE	DESCRIPTION	RATING
99%-100%	The school meets most or all standards of good repair. Deficiencies noted, if any, are not significant and/or impact a very small area of the school.	EXEMPLARY
90%-98.99%	The school is maintained in good repair with a number of non-critical deficiencies noted. These deficiencies are isolated, and/or resulting from minor wear and tear, and/or in the process of being mitigated.	GOOD
75.%-89.99%	The school is not in good repair. Some deficiencies noted are critical and/or widespread. Repairs and/or additional maintenance are necessary in several areas of the school site.	FAIR
0%-74.99%	The school facilities are in poor condition. Deficiencies of various degrees have been noted throughout the site. Major repairs and maintenance are necessary throughout the campus.	POOR

COMMENTS AND RATING EXPLANATION:	